

Office of the District Fire Officer North Fire Station, Karnataka Fire & Emergency Services B.M Road, Bengaluru..



No. 62/DFO/NFS/Bng/FSR/2022

Dated: 15-10-2022.

"Annexure-2"

To,
The Secretary,
St.SOPHIA CONVENT HIGH SCHOOL,
CA.6, 10th Block, 2ND Stage,BDA layout,
Nagarabhavi,Bengaluru-560072.

Sir,

Sub: Issue of <u>"Fire Safety Compliance report"</u> with respect to fire prevention, fire fighting and evacuation measures maintained at "M/s. St.SOPHIA CONVENT HIGH SCHOOL,CA.6, 10th Block, 2ND Stage,BDA layout, Nagarabhavi,Bengaluru-560072..." - reg.

Ref: 1) This office FSR No.62 /DFO/NFS/Bng/FSR/2022 Date: 15-10-2022.

2) Your request letter dated: 13-10-2022.

<<<>>>>

With reference to the above cited subject, as per ref(1), a conditional Fire Safety Recommendation was issued to the premises of "M/s. St.SOPHIA CONVENT HIGH SCHOOL, CA.6, 10th Block, 2ND Stage,BDA layout,Nagarabhavi,Bengaluru-560072." with a condition to fulfill the recommendations and compliance the same within 3 months.

With reference cited (2) above, the management of ". M/s. St.SOPHIA CONVENT HIGH SCHOOL" had requested for the fire safety compliance report from our department. In this regard the District fire officer, North Fire Station, Bengaluru was inspected on 15-10-2022 and submitted the report to issue fire safety Compliance report.

Under the above circumstance the Karnataka Fire & Emergency Services Department is issuing the "Fire Safety Compliance Report" to "M/s. St.SOPHIA CONVENT HIGH SCHOOL, CA.6, 10th Block, 2ND Stage,BDA layout,Nagarabhavi,Bengaluru-560072"

Subject to proper maintenance of fire fighting installations in the good working conditions, arrange for 40% of staffs/ employees training within 03 months from the date of issue of this report. "This report is valid up to only one year from the date of issue and is renewable without fail'.

Yours faithfully,

District Fire Officer
Karnataka State Fire & Emergency Services

North Fire Station, Mysore Road, Bangalore - 560 018.

ERE OF THE PROPERTY OF THE PRO



Office of the District Fire Officer, Karnataka Fire & Emergency Services, North Fire Station, B M Road, Bengaluru.



No. 62/DFO/NFS/Bng/FSR/2022

Dated: 15-10-2022.

ANNEXURE - 1

Group - B Educational Building

NBC-2016, Part-4, Table 7(11) 3.1.3 Group B Educational Buildings Sub Division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC-2016 are mandatory).

To,
The Secretary,
St.SOPHIA CONVENT HIGH SCHOOL,
CA.6, 10th Block, 2ND Stage,BDA layout,
Nagarabhavi,Bengaluru-560072.

Sir,

Sub: Issue of "Fire safety recommendation" with respect of fire prevention, fire fighting and evacuation measures required at "St.SOPHIA CONVENT HIGH SCHOOL,CA.6, 10th Block, 2ND Stage, BDA Layout ,Nagarabhavi, Bengaluru-560072." - reg.

Ref:

1) Your request letter dated: 13-10-2022.

<<<>>>

With reference to the subject cited above, the premises of "M/s St.SOPHIA CONVENT HIGH SCHOOL,CA.6, 10th Block, 2ND Stage, BDA Layout ,Nagarabhavi,Bengaluru-560072" was inspected by me on 15-10-2022 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under.

A. Details of the building / premises :-

01	Name and Address of the	:	The Secretary,
	Applicant.		Sri Kanaka Kalyana Mantapa Trust
60 m	AND EXPERIENCE FOR SHARLING WAY		CA.6 10 th Block, 2 nd stage, BDA layout, Nagarabhavi, Bengaluru-560072.
02	Name and Address of the premises.	:	St.SOPHIA CONVENT HIGH SCHOOL, CA.6, 10 th Block, 2 ND Stage, BDA Layout , Nagarabhavi, Bengaluru-560072.
03	Name and address of the	:	The Secretary,
	Building owner		Sri Kanaka Kalyana Mantana Trust
	transa 1 top wid- 13		CA.6 10 th Block, 2 nd stage, BDA layout.
04	Number of buildings	1	Nagarabhavi, Bengaluru-560072. 01 Building
05	Number of floors	*	round floor + 04 upper floors
	(SIG)	14	OE CONTRACTOR OF THE PROPERTY
	Tal Con	10	

	No. of entrances	01 entrance of 04.5	Complied.		
		been Provided from v	Complica.		
3.	Diesel generators.	One diesel generat	Complied.		
			capacity has been provided and it is		
		connected to all	, a		
		provisions in the build	_		
4.	Number of	No. of staircases	THE		
	staircases available	Width of staircases	1.80 mtrs each		
		Width of treads	di ventine i pria segui di		
	`	Height of risers	15 cms each	Complied.	
		Nos. of riser per flight	11 nos. each	42, 27	
		Height of handrails	External wall		
			each		
		Head room clearance	2.20 mtrs each	Author State Co.	
5.	Portable Fire	08 nos. ABC type ex			
	extinguishers	of 6 kgs capacity		Complied.	
		extinguishers, each of			
6	First aid hose reel	have been provided a Hose reel hose sy			
0	55	staircase has been pr			
	hose	reel hose of 19 m	24.5		
	Di Kasadhara	I STANSFALTER AND AND AND AND AND STANDARD TO SEE AND	7822006 304074262 Printfiller - 5252	Complied	
	1 5	adequate length to re		Complied.	
		point of the floor have	-101 CO 101 TO THE CO. CO.		
	20 75.00	with shut off branch			
	1.0	of 5 mm size. The	MANAGERINAL CONTRACTOR TO THE PERSON		
			have been connected at each landing.		
6.	Terrace tank over	The hose reel hose s			
	respective tower	connected to an ov	verhead tank of		
	terrace.	10 CONTROL 10 CO	ater capacity	Complied.	
		exclusively for firefigh	exclusively for firefighting purpose.		
7.	At the terrace tank	The hose reel hose s	system has been		
	level with	connected to Booste	r pump capable		
	minimum pressure	of delivering 900 LPN	A with minimum	Complied.	
	of 3.5 kg/cm ²	pressure of 3.5 kg/cm	2		
8.	Escape routes	Directions in which th	ne students have		
J		to move in the event	of an emergency		
	and the description	have been displayed		Complied.	
	[11 R	on each floor during e		- Indian	
9.	Fire order	'A notice board have			
٥.	(Fire Safety plans)	the action have been			
	(The Salety plans)	employees in case of			
	-	have been display	Compliad		
	(202)	1	Complied.		
	(EIR	telephone number of nearest fire			
	(S) 18 (1) (S)	station & 101, 500 550, & 600 and the nearest Ambulance service and Police			
	1001 000	nearest Ambulance se	ervice and Police		

		Station.		
10.	No smoking board.	No smoking boards have been		
		displayed.	Complied.	
11.	Fire siren	Fire siren has been installed.	Complied.	
12.	Fire Nodal Officer	Non teaching staff has been		
		appointed as a fire nodal officer.	Complied.	
13.	Fire Fighting	• ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	40% of the staffs/Teachers	
	training		shall be got trained in fire	
		Not Trained	prevention, fire fighting &	
			evacuation at	
		100	R.A.Mundkur fire &	
	- 1		emergency service	
			Academy, Bannerghatta	
			road, Bangalore-560 029.	

12. Fire precautionary measures :-

- A) Explosive and flammable materials should not be stores in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.
- B) Accumulation of combustible waste in and the premises should be avoided.
- C) The exit ways shall be always kept clear without any obstruction.
- D) Liquefied petroleum gas should not be stores in the building.
- E) The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
- F) During the class hours the class room doors shall not be locked from inside to out side.
- G) As per Honorable Supreme Court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year be conducting Fire Safety drills with co-ordinate Fire Service department.

Under the above circumstance, the Karnataka Fire & Emergency Services Department is issuing Fire Safety Recommendation to "St.SOPHIA CONVENT HIGH SCHOOL,CA.6, 10th Block, 2ND Stage, BDA Layout,Nagarabhavi,Bengaluru-560072." subject to condition and compliance of the above recommendations as shown in Column-13 of Part-B within 3 months and compliance from the undersigned.

"This Fire Safety Recommendation is valid for Only One Year from the date of issue and it is renewable.

All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.3 of Fire and Life safety will have to be complied with mandatorily.

Yours faithfully

District Fire Officer

Karnatake State Fire & Emergency Services
North Fire Station, Mysore Road,

Bangalore - 560 018.



ಚಲನ್ ಚಾಲ್ತಿ			na.		
ಲವಧಿ	ಜಿಲ್ಲೆ	ಇಲಾಖೆ	ಡಿಡಿಓ ಕಚೇರಿ DDO Office		
Challan Validity	District	Department			
7 Days	BENGALURU URBAN	DIVISIONAL FIRE OFFICE, KARNATAKA FIRE AND EMERGENCY SEVICES, BANGALORE SOUTH RANGE, BANGALORE			
ವರ್ಗ	ದಿನಾಂಕ	ಚಲನ್ ಉಲ್ಲೇಖ ಸಂಖ್ಯೆ	ಡಿಡಿಓ ಕೋದ್		
Category	Date	Challan Reference Number	DDO Code		
Government	15/10/2022	CR1022007000343809	140050		
ಸಂದಾಯದಾರನ					
ಹೆಸರು	STSOPHIA CONVENT HIGHSCHOOL				
Remitter Name					
ವಿಳಾಸ	CA (LOTH DI OCK 2NIC	STAGE BDA LAYOUT NAGA	DARIJAVI RENGALTIRI	1.560072	
Address	CA 6 10111 BLOCK 2ND	SINGE BDA LATOUT NAGA	RADITAVI DENGALORO	300072	
ಉದ್ದೇಶ	ಲೆಕ್ಕ ಶೀರ್ಷಿಕೆ	ಉಪ ಉದ್ದೇಶದ ಹೆಸರು	ಉದ್ದೇಶ ನಿರ್ದಿಪ್ಪ ಐಡಿ	ಮೊತ್ತ	
Purpose	Head of Account	Sub Purpose Name	Purpose Specific ID	Amount	
OTHER ITEMS- FIRE DEPARTMENT	. 0070~60~109~0~02~,000	12.FOR ISSUE OF ADVISE ON FIRE PREVENTION AND FIRE FIGHTING FOR NON HIGH RISE BUILDINGS.	NA-	20000	
ಸಂದಾಯದ					
ಬ್ಯಾಂಕ್	STATE BANK OF	ಒಟ್ಟು ಮೊತ್ತ		20000	
Remittance Bank	INDIA	Grand Total			
ಪಾವತಿ ಹಂತ	Payment Yet To Be	ಒಟ್ಟು ಮೊತ್ತ ಅಕ್ಷರಗಳಲ್ಲಿ			
Payment Status	Made At Agency Bank		SBI CLIS MARCHES BEACH PREMIATOR ONLY		
	ಹ		Branch 2	गलूर Tore	
ಪಾವತಿ ವಿಧ Payment Mode		Cash	CASH PAID FECEIVED / TRANS		
Payment Mode			Maker Checker 1 Checke	12	

Jr 187328130

District Fire Officer

Karlataka State Fire & Emergency Services

North Fire Stellon, Mysore Road,

Bangalore - 560 018.